TRITON Extreme Operating System Version 1.0.5
Improvement List

The following items describe the functional improvements and bug fixes included in this release

CompactFlash:
[Improvement of function]
The operating system has been improved to recognize the following CompactFlash media at start-up:
SanDisk SDCFB 1.0GB
SanDisk SDCFB 2.0GB
SanDisk SDCFH 512MB (Ultra 2)

Correction of Data:
[Pattern Data Correction]
The data in the following preset patterns have been corrected to reflect the following conditions:
011: Number of notes
046: Tempo Sync
047: Tempo Sync

Version 1.0.3 (B15)
Availability - May 2004

Common Mode:
[Improvement of function]
Certain characters or elements of some parameters and/or their values were not able to seen properly in the display. This has been improved.

[Bug fix]
When using the "Copy Valve Force" function in the Program/Combination/Sequencer/Sampling/ or Song Play modes, certain Valve Force parameters were not updated correctly. This has been fixed.

[Bug fix]
When using the "Copy Insert Effect" function in the Program/Combination/Sequencer/Sampling/ or Song Play modes, certain Valve Force parameters were not copied correctly. This has been fixed.

Program mode:
[Bug fix]
When working with a MOSS sound, any change of parameter in the Valve Force tab of page P9– such as "Placement" - was not reflected in the display.   This has been fixed.

Sequencer mode:
[Bug fix]
With the Valve Force Tab of P9 open, if you played back a song that had "Load FX?: OFF" as the first step (P1) in the "Cue List", the parameter "Ctrl.Ch" remained as being selected. This has been fixed.

[Bug fix]
If you pressed the [REC] -> [START] or [PAUSE] buttons while in the Valve Force Tab of page P9, the pop-up button for the upper track did not dim out. This has been fixed.

Song Play mode:
[Bug fix]
When accessing the "Jukebox" from the P3 Menu, the display did not always show the correct media type - such as "CDD:" -> "CF:". This has been fixed.

Global mode:
[Bug fix]
If the "USB Hub Power Exceeded!" message is being displayed, changing the state of the System Clock and then returning it to its original setting would cause the message to disappear, even though the situation still existed. This has been fixed.

[Bug fix]
If the MIDI OUT of a microKONTROL has connected to the MIDI IN of a TRITON Extreme, and the microKONTROL was turned on first, the TRITON Extreme would sometimes freeze up. This has been fixed.

Media mode:
[Bug fix]
When attempting to play back a .WAV file via the "CDD" drive from the Load/Save/Utility tab, the dimming of the EDIT Wave tab was not correct. This has been fixed

[Bug fix]
After using the "Delete", "Rename", etc. commands on a .wav file that had been inserted using the Make Audio CD tab, if the tab was selected again, the Edit WAVE tab did not dim. This has been fixed.

[Bug fix]
When using menu commands such as "Cut", "Paste", etc. in the Edit WAVE tab, with the overwrite box checked, sometimes the "Now Executing" message continued to be displayed. This has been fixed.

[Bug fix]
If an error occurred when trying to save a .SNG file, trying to save the file again could crash the system. This has been fixed.

[Bug fix]
If you attempted to use the menu command "Time Stretch (Sustaining)" in the Edit WAVE tab page, the "Not enough memory" message mistakenly appeared. This has been fixed.

[Bug fix]
When executing menu commands such as "Cut", "Clear", etc., to a WAVE file that had no data, the size of the file would increase or decrease. This has been fixed.

END.